

Inhaltsverzeichnis

SKDS Changelog (Version 2.0 -> 3.0) 3

SKDS Changelog (Version 2.0 -> 3.0)

Revision: 77

Author: steffen

Date: 09:38:01, Samstag, 22. September 2007

Message:

bugfix: skdsc : printout of key company & user-ID was swapped

bugfix: sample scripts were compiled with old, faulty standard-uds -lib

bugfix: standard-uds-lib replaced with tested version

cleanup: Installer now uses Desktop as default install directory to avoid confusion for non-admin users

Modified : /SKDS_Setup.nsi

Modified : /scripts/car-HSCAN.html

Modified : /scripts/car-HSCAN.sdl

Modified : /scripts/car-HSCAN.skd

Modified : /scripts/car-MSCAN.html

Modified : /scripts/car-MSCAN.sdl

Modified : /scripts/car-MSCAN.skd

Revision: 76

Author: steffen

Date: 09:29:50, Samstag, 22. September 2007

Message:

bugfix: standard-uds.pas was unfinished testversion

Modified : /scripts/standard-uds.pas

Revision: 75

Author: steffen

Date: 09:13:09, Samstag, 22. September 2007

Message:

cleanup: outcommented program code removed

cleanup: unused variable definitions removed

cleanup: unused Directive BUILDMASTER removed

release: "beta" removed in Program name

Modified : /Unit1.pas

Modified : /Unit2.pas

Modified : /Unit8.dfm

Modified : /build.templ

Modified : /heartbeat.dfm

Revision: 74

Author: steffen

Date: 11:43:42, Samstag, 15. September 2007

Message:

cleanup: Dongle valid time set to 365 days with 90 days prewarning
cleanup: needless buildmaster- define removed
bugfix: "Connected to" -information now shows real remote user, not just the selected username in the pulldown
cleanup: Remote connect timeout increased from 10 to 15 sec.for slow connections

Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /build.templ
Modified : /skdsutil.pas

Revision: 73

Author: steffen

Date: 10:17:03, Samstag, 15. September 2007

Message:

bugfix: timer present msgs contained randomly corrupt PCM Byte
feature: New extended Script function Getconfig to read parameter meaning out of config-database
feature: extended Script function OpenFile now with parameters to define Dialog Title and if file must already exist (to read from)

Modified : /configEdit.pas
Modified : /Unit2.pas

Revision: 72

Author: steffen

Date: 08:30:26, Sonntag, 9. September 2007

Message:

cleanup: standard-uds.pas with simplified configWrite call (but actual untested)

Modified : /scripts/standard-uds.pas

Revision: 71

Author: steffen

Date: 08:27:55, Sonntag, 9. September 2007

Message:

bugfix:standard-uds.pas now with length check whilre reading config- ACSII-FileDialog
feature: New Hyperterp- Function "FileDialog" (untested)

Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /scripts/standard-uds.pas

Revision: 70

Author: steffen

Date: 08:11:39, Sonntag, 2. September 2007

Message:

bugfix:standard-uds.pas : sec_access now working

bugfix:standard-uds.pas : Loadconfig with new Textload- routine

feature:standard-uds.pas : now also with flashvin

bugfix: (fs#36) configEdit: corrected Chksum- calculation

Modified : /configEdit.pas

Modified : /scripts/standard-uds.pas

Modified : /skds2.cfg

Revision: 69

Author: steffen

Date: 09:48:46, Sonntag, 26. August 2007

Message:

cleanup:Bussniffer now shows the direction of external messages correctly

feature:(fs#32) CS-Stick has now a limited lifetime

bugfix:(fs#17) Skype works now also for SKDS classic

bugfix:(fs#35) Update and Reload button work also after Module reload

Modified : /Unit1.pas

Modified : /Unit2.dfm

Modified : /Unit2.pas

Modified : /build.templ

Modified : /skdsutil.pas

Revision: 68

Author: steffen

Date: 07:31:28, Samstag, 25. August 2007

Message:

bugfig(fs#20) diagnostic mode is now correctly discovered on also on old KWP- Modules

bugfix:(fs#28) Multiframes are now sended correctly by SKDS. Before SKDS lost one byte after each Consecutive Frame

Modified : /Unit1.dfm

Modified : /Unit1.pas

Modified : /Unit2.dfm

Modified : /Unit2.pas

Revision: 67

Author: steffen

Date: 18:38:17, Montag, 20. August 2007

Message:

cleanup: adapted to Key Product code 1 instead 0
cleanup: Webinstaller now with automatic redirect to Download webpage in case automatic download fails

Modified : /WebSetup.nsi

Revision: 66

Author: steffen

Date: 07:08:22, Montag, 20. August 2007

Message:

feature: (fs#20) Bussniffer shows now all diagnostic msgs on the Bus

bug: Focus sticks on Userlist

Modified : /Unit1.dfm

Modified : /Unit1.pas

Modified : /Unit2.dfm

Modified : /Unit2.pas

Revision: 65

Author: steffen

Date: 12:19:46, Sonntag, 19. August 2007

Message:

bugfix: skype.pas answers now also the WM_QUERYENSESSION -Msg correctly, so that Windows now shut down correctly again

Modified : /build.templ

Revision: 64

Author: steffen

Date: 14:23:11, Samstag, 18. August 2007

Message:

bugfix; (fs#31) Userlist will not updated any more when user just select contact

cleanup:Version number of all tools now equal

feature: Dongle now uses release company code

cleanup: skdsc now disables read and execute control with anonymous key

Modified : /Unit1.pas

Modified : /Unit8.pas

Modified : /build.templ

Modified : /skdsutil.pas

Revision: 63

Author: steffen

Date: 18:23:48, Montag, 6. August 2007

Message:

Some Module scripts added to repository

```
-----  
Added : /scripts/car-HSCAN.html  
Added : /scripts/car-HSCAN.htp  
Added : /scripts/car-HSCAN.sdl  
Added : /scripts/car-HSCAN.skd  
Added : /scripts/car-MSCAN.html  
Added : /scripts/car-MSCAN.htp  
Added : /scripts/car-MSCAN.sdl  
Added : /scripts/car-MSCAN.skd  
Deleted : /scripts/EUCD-HSCAN.html  
Deleted : /scripts/EUCD-HSCAN.htp  
Deleted : /scripts/EUCD-HSCAN.sdl  
Deleted : /scripts/EUCD-HSCAN.skd  
Deleted : /scripts/EUCD-MSCAN.htp  
Deleted : /scripts/EUCD-MSCAN.sdl  
Deleted : /scripts/EUCD-MSCAN.skd  
Modified : /scripts/standard-uds.pas  
Modified : /skds2.cfg  
Modified : /skds2.dof
```

Revision: 62

Author: steffen

Date: 14:05:27, Samstag, 21. Juli 2007

Message:

Bugfix: Changing the ModuleID stops the Testerpresent now

Bugfix: Modul - State is now also remotely reported back to the main window

bugfix: configEdit does now calculate the Checksum correctly

bugfix: setbuild now works independend from svn installation path

```
-----  
Modified : /configEdit.pas  
Modified : /Unit1.dfm  
Modified : /Unit1.pas  
Modified : /Unit2.pas  
Modified : /setbuild.bat  
Modified : /skdsutil.pas
```

Revision: 61

Author: steffen

Date: 10:07:59, Sonntag, 15. Juli 2007

Message:

feature: config- Edit completed

feature: new function udsEditconfig

feature: Search -functions in configEdit and Mainform

bugfix: received multiframe telegrams now shown with the right direction in BusSniffer

bugfix: last bus error now correctly shown in statusbar

```
-----  
Modified : /configEdit.dfm
```

```
Modified : /configEdit.pas  
Modified : /CreateStick.hta  
Modified : /Unit1.dfm  
Modified : /Unit1.pas  
Modified : /Unit2.pas  
Modified : /configdb.pas
```

Revision: 60

Author: steffen

Date: 10:14:34, Samstag, 14. Juli 2007

Message:

bugfix: Zugriffsverletzung bei Update- und Timer Button ohne geöffnetes Script behoben

feature : Vehicle Config - Editor & Datenbank teilweise implementiert

```
Added : /configEdit.dfm  
Added : /configEdit.pas  
Modified : /Unit1.dfm  
Modified : /Unit1.pas  
Modified : /Unit2.dfm  
Modified : /Unit2.pas  
Added : /configdb.pas  
Modified : /credits.dfm  
Added : /db/config.csv  
Modified : /skds2.cfg  
Modified : /skds2.dof  
Modified : /skds2.dpr
```

Revision: 59

Author: steffen

Date: 13:53:47, Samstag, 7. Juli 2007

Message:

bugfix: Modul OP- State wird nun local und remote bis zum Anzeigefenster durchgereicht

bugfix: Indicator- Fenster reagiert nun korrekt auf Größenänderungen

bugfix: CreateStick kopiert jetzt auch die DTC- DB

minor: Code clean up in SKDSC

```
Modified : /CreateStick.hta  
Modified : /Indicator.dfm  
Modified : /Indicator.pas  
Modified : /Unit1.pas  
Modified : /Unit2.pas
```

Revision: 58

Author: steffen

Date: 07:39:59, Samstag, 7. Juli 2007

Message:

Indikator Fenster hinzugefügt

Added : /Indicator.dfm
Added : /Indicator.pas
Modified : /Unit1.pas
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /skds2.cfg
Modified : /skds2.dpr

Revision: 57
Author: steffen
Date: 10:58:00, Sonntag, 1. Juli 2007
Message:
Online check for latest version is now working

Modified : /build.templ
Deleted : /makeinstalldir.bat
Modified : /skds2.cfg
Modified : /skds2.dof

Revision: 56
Author: steffen
Date: 08:19:42, Sonntag, 1. Juli 2007
Message:
bugfix: Stick Installer kopierte SKDS3.exe nicht mit
cleanup: Fenster-Titel unvollständig
bugfix: Uninstaller löschte nicht alle files

Modified : /CreateStick.hta
Modified : /SKDS_Setup.nsi
Modified : /Unit1.dfm
Modified : /Unit1.pas

Revision: 55
Author: steffen
Date: 07:47:22, Sonntag, 1. Juli 2007
Message:
bugfix: DTC -DB Klartext wurde nicht angezeigt
cleanup: Credits Text um (C) und Website erweitert
feature: HyperTerp Help im Installer ergänzt
feature: SKDS Classic im Installer ergänzt
cleanup: Fehler im EUCD- Demoscript behoben
cleanup: uds- Standardbibliothek ergänzt
bugfix: Senden von Multiframes

Modified : /SKDS_Setup.nsi
Modified : /Unit1.dfm

Modified : /Unit1.pas
Modified : /Unit8.dfm
Modified : /Unit8.pas
Modified : /credits.dfm
Modified : /credits.pas
Added : /htrplang.hlp
Modified : /scripts/EUCD-HSCAN.html
Modified : /scripts/EUCD-HSCAN.htp
Modified : /scripts/EUCD-HSCAN.sdl
Modified : /scripts/EUCD-HSCAN.skd
Deleted : /scripts/standard-uds.htp
Added : /scripts/standard-uds.pas
Modified : /skdsutil.pas

Revision: 54

Author: steffen

Date: 13:46:25, Sonntag, 17. Juni 2007

Message:

several files for CreateStick- Program added
CreateStick.hta for copy all files to USB-Stick implemented
small color bug in Update-Icon removed

Modified : /CreateStick.hta
Modified : /SKDS_Setup.nsi
Modified : /Unit1.dfm
Added : /WebSetup.nsi
Modified : /icons/yellow_reload.bmp
Added : /skds.PNG

Revision: 53

Author: steffen

Date: 12:59:15, Sonntag, 17. Juni 2007

Message:

(FS#10) No redial possible after calling normal user fixed
(FS#26) Autoconnect feature implemented
(FS#23) Hotkeys for Table updates implemented

Modified : /Unit1.dfm
Modified : /Unit1.pas
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /Unit7.dfm
Modified : /Unit7.pas
Modified : /heartbeat.dfm

Revision: 52

Author: steffen

Date: 14:31:21, Sonntag, 10. Juni 2007

Message:

überarbeitete Routinen für Tester present auch bei KWP- Singleframe telegrammen,

Bus sniffer- Layout dem des Canalyzers angepasst

Modified : /Unit1.dfm
Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /icons/yellow_reload.bmp
Modified : /icons/yellow_reload.svg
Modified : /skdsutil.pas

Revision: 51

Author: steffen

Date: 12:20:46, Samstag, 2. Juni 2007

Message:

Struktur für NSIS- Installer angepasst, Sample- scripts aufgenommen, NSIS - Scripte ergänzt, ebenso CreateStick, skdsc und SKDSViewer mit ins Packet genommen

Added : /CreateStick.hta
Added : /SKDS_Setup.nsi
Modified : /Unit1.dfm
Added : /licence.txt
Added : /scripts
Added : /scripts/EUCD-HSCAN.html
Added : /scripts/EUCD-HSCAN.htp
Added : /scripts/EUCD-HSCAN.sdl
Added : /scripts/EUCD-HSCAN.skd
Added : /scripts/EUCD-MSCAN.htp
Added : /scripts/EUCD-MSCAN.sdl
Added : /scripts/EUCD-MSCAN.skd
Added : /scripts/standard-uds.htp
Added : /www.skds.de.url

Revision: 50

Author: steffen

Date: 18:53:36, Montag, 28. Mai 2007

Message:

Läuft jetzt im Remote- Betrieb, wenn keinerlei installierte CAN- Hardware gefunden werden kann

Modified : /Unit1.pas

Revision: 49

Author: steffen

Date: 12:59:43, Sonntag, 20. Mai 2007

Message:

Relative Timeticks jetzt auch bei TransPacket, nicht nur in transtele

OK Buton im Credits- Window wieder gelöscht

Modified : /credits.dfm

Modified : /credits.pas

Modified : /skdsutil.pas

Revision: 48

Author: steffen

Date: 22:00:22, Samstag, 19. Mai 2007

Message:

CodeMeter-Key und dynamische CodeMeter-DLL implementiert

Modified : /skds2.cfg

Modified : /skds2.dpr

Revision: 47

Author: steffen

Date: 16:48:48, Samstag, 19. Mai 2007

Message:

Relativer Tickcount im Snifferfenster, startet nach jedem Clear- Button wieder bei 0

Modified : /Unit1.pas

Modified : /skdsutil.pas

Revision: 46

Author: steffen

Date: 16:43:30, Sonntag, 13. Mai 2007

Message:

Alte hässliche TextButtons aus der oberen Menuleiste entfernt und durch bunte Knöpfchen ersetzt bzw. ins "View"- Menü verschoben.

Credit- Text vervollständigt

Modified : /Unit1.dfm

Modified : /Unit2.dfm

Modified : /Unit2.pas

Modified : /credits.dfm

Modified : /credits.rtf

Revision: 45

Author: steffen

Date: 18:02:11, Samstag, 12. Mai 2007

Message:

Buttons implementiert

Modified : /Unit1.dfm
Modified : /Unit1.pas
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /Unit6.dfm
Added : /credits.rtf
Added : /icons/blue_Disk.bmp
Deleted : /icons/blue_cancel.svg
Added : /icons/blue_timer_2.bmp
Added : /icons/green_scanner.svg
Deleted : /icons/stock_delete.bmp
Deleted : /icons/stock_delete.png
Deleted : /icons/stock_refresh.bmp
Deleted : /icons/stock_refresh.png
Deleted : /icons/stock_save_as.bmp
Deleted : /icons/stock_save_as.png
Added : /icons/yellow_reload.bmp
Added : /icons/yellow_reload.svg

Revision: 44

Author: steffen

Date: 08:59:52, Samstag, 12. Mai 2007

Message:

Erste Credits, timerbutton teilweise eingerichtet...

Modified : /Unit1.dfm
Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /credits.dfm

Revision: 43

Author: steffen

Date: 18:20:18, Sonntag, 6. Mai 2007

Message:

More SVG- icons

Deleted : /icons/blue_Diosk.svg
Added : /icons/blue_Disk.svg(Copy from path: /icons/blue_Diosk.svg,
Revision, 42
Added : /icons/blue_timer.svg

Revision: 42

Author: steffen

Date: 18:31:34, Dienstag, 1. Mai 2007

Message:

Ein paar Icons dazu...

Added : /icons/blue_Diosk.svg
Added : /icons/blue_cancel.svg
Added : /icons/green_cancel.svg
Added : /icons/grey_cancel.svg
Added : /icons/red_cancel.svg

Revision: 41

Author: steffen

Date: 09:42:02, Sonntag, 22. April 2007

Message:

Automatische Breitenberechnung nach jedem Kommando
Builversion- dtemplate an das Problem mit diesem SubWCRev- Programm
angepasst

Modified : /Unit1.pas
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /build.templ

Revision: 40

Author: steffen

Date: 09:12:59, Sonntag, 22. April 2007

Message:

Mit Credirs angefangen,Dispatcher- Destructor implementiert und mit dem
Buildate/ Buildver muß ich auch noch was zusammentricksen :-)

Modified : /Unit1.dfm
Modified : /Unit1.pas
Modified : /Unit2.pas
Added : /credits.dfm
Added : /credits.pas
Modified : /skds2.cfg
Modified : /skds2.dpr

Revision: 39

Author: steffen

Date: 12:18:45, Samstag, 7. April 2007

Message:

Besseres Erkennen des OP- Modes (FS#16)
Bussniffer re- aktivieren (FS#7)
Sofortiges Auflegen der Clients (FS#9)
Rote Farbe für's Connect- Gauge (FS#8)
Bussniffer- Window Beautification
Online Manual & Bugtracker (FS#5)

Modified : /Unit1.dfm
Modified : /Unit1.pas

```
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /Unit6.dfm
Modified : /Unit6.pas
Modified : /build.templ
Modified : /heartbeat.pas
Added : /icons
Added : /icons/stock_delete.bmp
Added : /icons/stock_delete.png
Added : /icons/stock_refresh.bmp
Added : /icons/stock_refresh.png
Added : /icons/stock_save_as.bmp
Added : /icons/stock_save_as.png
Modified : /skds2.dpr
Modified : /skdsutil.pas
```

Revision: 38

Author: steffen

Date: 07:55:02, Donnerstag, 5. April 2007

Message:

Die bislang verwendeten numerischen Error-Werte beim Bustransfer
zumindestens vorwiegend gegen Konstanten ausgetauscht.

Fehlersituationen beim Abziehen des CAN- Bus oder der CanCard soweit
abgefangen, daß im Fall des Busleitung selber ein Weiterarbeiten möglich und
im Fall der Karte wenigstens ein problemloses, d.h. absturzfrees Beenden
möglich ist.

Last not least habe ich auch noch die Bilder- Ursprungsdateien mit ins
Archiv übernommen, falls man das Design später noch mal ändern muß.

```
Modified : /Unit1.pas
Modified : /Unit2.pas
Added : /callbutton.xcf
Added : /car_256colors.bmp
Modified : /skdsutil.pas
```

Revision: 37

Author: steffen

Date: 14:10:53, Montag, 2. April 2007

Message:

Jetzt mit dynamischer WIBU- Key- Laderoutine

```
Modified : /Unit1.pas
Modified : /Unit8.pas
Modified : /skds2.dpr
```

Revision: 36

Author: steffen
Date: 11:34:21, Montag, 2. April 2007
Message:
Viele kleine Updates:
Dongle jetzt aus beiden Richtungen möglich
Demo- Mode ohne Schlüssel
Neues Call- Button Design
Neues SKDS- Icon
viele kleine Bugfixes

Modified : /Unit1.dfm
Modified : /Unit1.pas
Modified : /Unit11.dfm
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /Unit6.dfm
Modified : /Unit7.dfm
Modified : /Unit8.dfm
Added : /callbutton.bmp
Modified : /car.ico
Modified : /car2.ico
Modified : /heartbeat.dfm
Modified : /heartbeat.pas
Modified : /skds2.res
Modified : /skdsutil.pas

Revision: 35
Author: steffen
Date: 11:46:10, Freitag, 30. März 2007
Message:
Relativ stabiles An- und Abgemelde der Skype- Verbindung

Modified : /Unit1.pas
Modified : /heartbeat.dfm
Modified : /heartbeat.pas
Modified : /skds2.dpr

Revision: 34
Author: steffen
Date: 22:56:15, Donnerstag, 29. März 2007
Message:
Versuch mit Auf-und Abbauen der Skype- Verbindung

Modified : /Unit1.pas
Deleted : /build.pas
Added : /build.templ
Added : /setbuild.bat

Revision: 33
Author: steffen
Date: 14:41:20, Donnerstag, 29. März 2007
Message:
Auflegen der Verbindung vom Slave aus scheint jetzt zu funktionieren

Modified : /Unit1.pas
Modified : /heartbeat.pas

Revision: 32
Author: steffen
Date: 13:26:04, Donnerstag, 29. März 2007
Message:

Added : /heartbeat.dfm

Revision: 31
Author: steffen
Date: 13:24:58, Donnerstag, 29. März 2007
Message:

Added : /heartbeat.pas

Revision: 30
Author: steffen
Date: 12:51:41, Donnerstag, 29. März 2007
Message:
Versuch, das Beenden der Skype-Applikation beim Auflegen zu realisieren
(leider noch buggy)

Modified : /Unit1.pas
Modified : /build.pas
Modified : /skds2.cfg
Modified : /skds2.dpr

Revision: 29
Author: steffen
Date: 13:28:02, Montag, 26. März 2007
Message:
relative unitnames and obsolete functions removed

Modified : /Unit2.pas
Modified : /skds2.cfg
Modified : /skds2.dof

Revision: 28
Author: steffen
Date: 09:27:17, Montag, 26. März 2007
Message:
erste Versuche mit dynamischer Library und Skype-line

Modified : /build.pas
Modified : /skds2.dpr

Revision: 27
Author: steffen
Date: 19:41:39, Freitag, 2. März 2007
Message:
jetzt aber: Presenttimer in Unit2.pas gekillt

Modified : /Unit1.pas
Modified : /Unit2.pas

Revision: 26
Author: steffen
Date: 19:14:20, Freitag, 2. März 2007
Message:
den bösen Presenttimer in Unit 2 entfernt

Modified : /Unit1.pas
Deleted : /Unit12.dfm
Deleted : /Unit12.pas
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /Unit7.dfm
Modified : /Unit7.pas
Modified : /Unit8.dfm
Modified : /Unit8.pas
Modified : /skds2.dpr

Revision: 25
Author: steffen
Date: 16:20:32, Freitag, 2. März 2007
Message:
zentralen Testerpresent- Timer im Scanner-Modul eingebaut

Modified : /CANlibD.pas
Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /Unit9.dfm
Modified : /Unit9.pas
Modified : /build.pas
Modified : /skdsutil.pas

Modified : /testscripts/uds_Test.htp

Added : /testscripts/epb.htp

Revision: 24

Author: steffen

Date: 09:22:58, Montag, 21. August 2006

Message:

Schlüsselabfrage zum Aufruf von Skype eingebaut

Modified : /Unit1.dfm

Modified : /Unit2.pas

Revision: 23

Author: steffen

Date: 09:20:44, Montag, 21. August 2006

Message:

Schlüsselabfrage zum Aufruf von Skype eingebaut

Modified : /Unit1.pas

Modified : /build.pas

Revision: 22

Author: steffen

Date: 13:42:59, Sonntag, 20. August 2006

Message:

Now Skype also works with Diagnostics

Diag- Timer moved in single unit scanner

Modified : /build.pas

Modified : /skds2.dpr

Revision: 21

Author: steffen

Date: 19:09:21, Samstag, 19. August 2006

Message:

Möglicherweise lauffähig mit Skype

Modified : /Unit1.pas

Modified : /build.pas

Modified : /skds2.dpr

Revision: 20

Author: steffen

Date: 22:00:42, Donnerstag, 17. August 2006

Message:

Umbauten, um Senduds Skype-fähig zu bekommen

Modified : /Unit1.pas
Modified : /Unit2.dfm
Modified : /Unit2.pas
Modified : /build.pas

Revision: 19
Author: steffen
Date: 18:42:23, Montag, 14. August 2006
Message:
Nach Skype- Verlust erstmals wieder lauffähig

Modified : /Unit1.dfm
Modified : /Unit8.dfm
Modified : /build.pas
Modified : /skds2.cfg
Modified : /skds2.dof
Modified : /skds2.dpr

Revision: 18
Author: steffen
Date: 00:30:42, Donnerstag, 22. Juni 2006
Message:
Temporary level with flushbuffer as workaround because of some unclear generation of CF- Frames

Modified : /Unit1.pas
Modified : /Unit2.pas

Revision: 17
Author: steffen
Date: 00:17:45, Mittwoch, 14. Juni 2006
Message:
UDSset and udsGet seems to work now

Modified : /Unit2.pas

Revision: 16
Author: steffen
Date: 12:26:06, Samstag, 10. Juni 2006
Message:
now with corrected length in udsSet() function (+1)

Modified : /Unit2.pas
Modified : /build.pas
Added : /db
Added : /db/DTC.csv

Revision: 15
Author: steffen
Date: 00:53:34, Donnerstag, 8. Juni 2006
Message:
load and save buffer now implemented

Modified : /Unit2.pas
Modified : /build.pas
Modified : /testscripts/uds_Test.htp

Revision: 14
Author: steffen
Date: 00:54:47, Mittwoch, 7. Juni 2006
Message:
load and SaveBuffer - untested

Modified : /Unit2.pas
Modified : /build.pas

Revision: 13
Author: steffen
Date: 00:57:39, Dienstag, 6. Juni 2006
Message:
Zwischenstand für files in den Buffer

Modified : /Unit2.pas
Modified : /build.pas
Modified : /skdsutil.pas

Revision: 12
Author: steffen
Date: 00:47:53, Mittwoch, 24. Mai 2006
Message:
Now with unlimited buffer size (UDSget, set, clear and len)

Modified : /Unit1.dfm
Modified : /Unit2.pas
Modified : /build.pas
Modified : /skdsutil.pas
Modified : /testscripts/uds_Test.htp

Revision: 11
Author: steffen
Date: 00:16:48, Montag, 8. Mai 2006
Message:
Angeblich erste Erfolge mit UDS, DTC - Datenbank Mylittlebase ergänzt

Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /build.pas
Added : /mldb.pas
Modified : /skds2.dpr
Modified : /testscripts/uds_Test.htp

Revision: 10
Author: steffen
Date: 00:25:04, Sonntag, 26. März 2006
Message:

First Version with Skype- Function

Modified : /Unit1.dfm
Modified : /build.pas

Revision: 9
Author: steffen
Date: 07:49:39, Sonntag, 12. März 2006
Message:

No, this is the first runnable version

Modified : /Unit2.pas

Revision: 8
Author: steffen
Date: 07:48:23, Sonntag, 12. März 2006
Message:

first runnable version with uds

Modified : /Unit1.dfm
Modified : /Unit2.pas
Modified : /build.pas
Added : /testscripts
Added : /testscripts/uds_Test.htp

Revision: 7
Author: steffen
Date: 11:59:23, Samstag, 4. März 2006
Message:

First trials for multiframe

Modified : /Unit2.pas
Modified : /build.pas
Modified : /skdsutil.pas

Revision: 6
Author: steffen
Date: 23:47:21, Donnerstag, 26. Januar 2006
Message:
check in latest level to compare changes to integrate into skds_classic

Modified : /Unit1.pas
Modified : /build.pas

Revision: 5
Author: steffen
Date: 14:48:39, Sonntag, 22. Januar 2006
Message:
erste scheinbar vollständige sendKWP- Version, noch nicht voll lauffähig

Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /Unit9.pas

Revision: 4
Author: steffen
Date: 04:33:05, Sonntag, 22. Januar 2006
Message:
With first local implemented dispatcher

Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /Unit9.pas
Modified : /build.pas
Deleted : /dispatcher.pas
Modified : /skds2.dpr

Revision: 3
Author: steffen
Date: 23:52:38, Freitag, 20. Januar 2006
Message:
First integration of the new skype dispatcher

Modified : /Unit1.dfm
Modified : /Unit1.pas
Modified : /Unit2.pas
Modified : /Unit9.pas
Modified : /build.pas
Modified : /dispatcher.pas
Modified : /skds2.dpr

Revision: 2

Author: steffen
Date: 14:31:56, Montag, 9. Januar 2006
Message:
started with the dispatcher.pas

Modified : /build.pas
Added : /dispatcher.pas
Modified : /skds2.dpr

Revision: 1
Author: steffen
Date: 10:58:47, Sonntag, 8. Januar 2006
Message:
Initial Import

Added : /CANlibD.pas
Added : /Unit1.dfm
Added : /Unit1.pas
Added : /Unit10.dfm
Added : /Unit10.pas
Added : /Unit11.dfm
Added : /Unit11.pas
Added : /Unit12.dfm
Added : /Unit12.pas
Added : /Unit2.dfm
Added : /Unit2.pas
Added : /Unit3.dfm
Added : /Unit3.pas
Added : /Unit6.dfm
Added : /Unit6.pas
Added : /Unit7.dfm
Added : /Unit7.pas
Added : /Unit8.dfm
Added : /Unit8.pas
Added : /Unit9.dfm
Added : /Unit9.pas
Added : /build.pas
Added : /car.ico
Added : /car2.ico
Added : /isu.bmp
Added : /makeinstalldir.bat
Added : /siemens.bmp
Added : /skds-sw.bmp
Added : /skds.bmp
Added : /skds.ico
Added : /skds2.cfg
Added : /skds2.dof
Added : /skds2.dpr
Added : /skds2.res
Added : /skds_small.bmp

```
Added : /skdscan2.res
Added : /skdsutil.pas
Added : /unit13.dfm
Added : /unit13.pas
Added : /unit4.dfm
Added : /unit4.pas
Added : /unit5.pas
Added : /vcand32.dll
```

From:

<http://www.koehlers.de/wiki/> - **Steffen Köhlers Online- Bastelbuch**

Permanent link:

http://www.koehlers.de/wiki/doku.php?id=skdsdocu:changelog_30

Last update: **2010/07/24 14:13**

